Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 1244
 2580 EAST 19TH ST/MANH
 NY Spills
 S102145823

 ENE
 2580 EAST 19TH STREET
 N/A

> 1 1.610 mi. 8501 ft.

Relative: SPILLS:

NEW YORK CITY, NY

 Higher
 Name:
 2580 EAST 19TH ST/MANH

 Actual:
 Address:
 2580 EAST 19TH STREET

 10 ft.
 City,State,Zip:
 NEW YORK CITY, NY

 Spill Number/Closed Date:
 9002501 / 1990-06-05

 Facility ID:
 9002501

 Facility Type:
 ER

 DER Facility ID:
 75079

 Site ID:
 81107

 DEC Region:
 2

Spill Cause: Equipment Failure Spill Class: Not reported SWIS: 3101 Spill Date: 1990-05-31 Investigator: **KSTANG** Referred To: Not reported Reported to Dept: 1990-06-04 CID: Not reported Water Affected: Not reported Spill Source: Commercial Vehicle Spill Notifier: Affected Persons

Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Cleanup Ceased:

Date Entered In Computer: 1990-06-13
Spill Record Last Update: 2004-09-30
Spiller Name: Not reported
Spiller Company: NYCDOS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

TANG '

Remarks: "OIL FOUND ON STREET, SUSPECT HOSE ON GARBAGE TRUCK BURST, NYCDOS DID

CLEAN UP."

1990-06-05

All Materials:

 Site ID:
 81107

 Operable Unit ID:
 942357

 Operable Unit:
 01

 Material ID:
 437245

 Material Code:
 0022

Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00

Oxygenate: Not reported

Site ID: 81107

Map ID Direction Distance Elevation

Site

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

Operable Unit ID: 942357
Operable Unit: 01
Material ID: 437244
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Units: Not reported

Recovered: .00

Oxygenate: Not reported